

Giling Computer Applications

GCA93 Fused current detector with fault indication
Special list for Maerklin ground detection

Revised: July 11, 2012

Quantity	Reference	Part
8	R1 .. R8	resistor 33 Ohm
0	R9 .. R16	Not used
1	RP1	ARRAY 8 x 10K
0	GR1 .. GR8	not used
2	U1,U2	LTV844 OR 2 x LTV824
1	J1	3 x AK012-03 (Reichelt)
8	F1 .. F8	Resistor 4,7 KOhm
1	J3	PSS 254/10G (Reichelt)
0	D1 .. D8	Not used
0	Led1 .. Led8	Not used
8	Led9 .. Led16	LED 3mm high luminance (clear type)
1	connector	PSK254/10W
10	pins	PSK
4	support	M4x10
4	Screw	M4x8
1	PCBoard	GCA93

Giling Computer Applications

GCA93 Fused current detector with fault indication
Special list for Maerklin ground detection

Revised: July 11, 2012

Quantity	Reference	Part
8	R1 .. R8	resistor 33 Ohm
0	R9 .. R16	Not used
1	RP1	ARRAY 8 x 10K
0	GR1 .. GR8	not used
2	U1,U2	LTV844 OR 2 x LTV824
1	J1	3 x AK012-03 (Reichelt)
8	F1 .. F8	Resistor 4,7 KOhm
1	J3	PSS 254/10G (Reichelt)
0	D1 .. D8	Not used
0	Led1 .. Led8	Not used
8	Led9 .. Led16	LED 3mm high luminance (clear type)
1	connector	PSK254/10W
10	pins	PSK
4	support	M4x10
4	Screw	M4x8
1	PCBoard	GCA93