



www.phellings.net
 email : peter@hellings.net
 Title : 8-Input Hall sensor unit for long wiring.
 Size : Document Number : GCA179
 B : 1.1
 Date : July 17, 2014 Sheet 1 of 1